


Ver.	SQUARES 111x1	SQUARES 111x2
M	173	173
L	173	333



1

min. 120

~230 V

push

L N PE

OFF

5

180°

2

6

Gu10

3

7

4

8

9

ON

180°

